

Maintenance Request

Request:	9216	Property:	4335 Crow Road
Description:	While at the apartment for pestcontrol the rain came pouring in the back door.looks to be pooling under the floor.		Willow Chase Apts Beaumont, TX 77706
Category:	Other1	Unit:	1C (4335 Crow Road)
Status:	Scheduled	Tenant:	Crystal Broyles
Completion Date:		Caller's Name:	Crystal Broyles
Priority:	High	Caller's Phone:	(580) 579-7855
Call Date:	08/06/2026 01:11 PM	Caller's Email:	cryssytigger2@aol.com
Due By:		Tech Notes:	
Permission to Enter:	Yes	Access Notes:	Call before entering,pets inside Crystal Broyles (580) 579-7855
Vendor:	Stanley Holmes, Beaumont		
User:	Tina Hulse		



