

Maintenance Request

Request:	9396	Property:	4335 Crow Road
Description:	Toilet slowly flushes and shower slowly drains. The plumbing drain outside my apartment door I think is clogged. I see water on the ground. Photo attached.		Willow Chase Apts
Category:	plumbing	Unit:	Beaumont, TX 77706
Status:	Scheduled	Tenant:	3D (4335 Crow Road)
Completion Date:		Caller's Name:	Jacob Seguin
Priority:	High	Caller's Phone:	(210) 789-4033
Call Date:	09/03/2026 10:55 AM	Caller's Email:	jacob11.js@gmail.com
Due By:		Tech Notes:	
Permission to Enter:	Yes	Access Notes:	Key is in the office, probably the pump issue.,
Vendor:	Stanley Holmes, Beaumont		
User:	Tina Hulse		

