

Maintenance Request

Request:	9388	Property:	4335 Crow Road
Description:	Toilet is running non stop but not flushing, water is gushing out the ground with sewage, water pressure is low in the bathroom		Willow Chase Apts Beaumont, TX 77706
Category:	plumbing	Unit:	4D (4335 Crow Road)
Status:	Scheduled	Tenant:	Harlan Charles
Completion Date:		Caller's Name:	Chelsea Doneghy
Priority:	Critical	Caller's Phone:	(409) 781-6921
Call Date:	09/02/2026 09:39 PM	Caller's Email:	chelsea.1123@hotmail.com
Due By:		Tech Notes:	
Permission to Enter:	Yes	Access Notes:	Keys in the office, same i'm sure
Vendor:	Stanley Holmes, Beaumont		
User:	Tina Hulse		